


ISSUE	SUMMARY	
1	INITIAL ISSUE	11 DEC. 08
2	FUEL SPILL ALM	22 JUN. 09
3	ADDED RATINGS	27 JAN 11

ENGINE FAILURE ALARM

PUMPHOUSE TROUBLE ALARM (OPTIONAL)



GOLD FLASH
 ALARM CONTACTS RATED:
 10A @ 28VDC
 10A @ 120VAC
 3A @ 120VDC

EXTERNAL DIAGRAM FOR OPT. 7 INDIVIDUAL ALARM CONTACTS IN SERIES DMC CONTROLLERS	
MASTER CONTROL SYSTEMS INC. LAKE BLUFF, ILLINOIS U.S.A.	
USED ON	REPLOT 27 JAN 11
DRN.	DES.
APP.	DATE 11 DEC. 08
DWG. 18730	ISS. 3 SHEET 1 OF 1